



## IDDE Program Dry Weather Screening SOP/Checklist

### Pre-inspection Items

- Map Outfalls
- Develop outfall inspection priority schedule
- Proper equipment
  - Clear sampling jar
  - Map showing location
  - *Dry Weather Screening and Visual Water Discharge Examination Report*
  - Camera
  - GPS unit if applicable

### Inspection (Use IDDE Dry Weather Screening Flowchart)

- Check for dry weather discharge
- If discharge is present – pull sample. If no discharge – document findings.
- Follow procedures on **Flowchart** and **Examination Report** as applicable
- Photo and document findings
- If there are problems and/or cause for concern move to inspection follow-up procedures

### Inspection Follow-Up Procedures

- File any Photos
- If appropriate, call either North Logan Fire Department or Bear River Health Department for advice and to report findings
  - North Logan Fire Department through Dispatch Center (435) 755-5739
  - Bear River Health Department (435) 792-6500 or after hours (435) 716-8771
- Trace discharge upstream by checking manholes – 1,000 foot intervals
- Find last manhole with any evidence of illicit discharge
- Look at surface improvements in the area to determine possible suspects
- If determination cannot be made from the surface investigations, then TV or smoke test line for unknown connections.
- Document findings